

Surface Finishing

Make protection, appearance and functional fit work together.



Manufacturing reference. Material records and the order specification establish the actual grade and supplied scope.

01 / Choose a defined process

State the requested anodizing, hard anodizing, blasting, brushing, powder coating, screen printing or laser marking. Suitability depends on material and part requirements.

02 / Control what changes

Define thickness, color or sample, texture, rack/contact marks and masking. Protect bearing seats, threads, sealing faces and electrical contacts as required.

03 / Inspect the delivered condition

Specify final dimension limits and appearance acceptance. Request treatment records or tests only when the method and criteria have been agreed.

Use with the released drawing. The quotation confirms capability, responsibilities, price and timing for your project.

Your quotation checklist.

Share what you have. Identify the open decisions before the part is released.

- ☐ Material grade and pre-finish condition
- ☐ Process and governing finish specification
- ☐ Thickness, color/sample and texture direction
- ☐ Masking map for functional interfaces
- ☐ Artwork and position for printing or marking
- ☐ Final dimensions, batch and evidence requirements

Agree the acceptance package.

1. Agree the appearance reference and viewing condition.
2. Define masking and acceptable contact marks.
3. Inspect critical fits in the final condition.
4. Confirm any required test and reporting scope.

Confidential drawing? Arrange an NDA before sharing sensitive files. Begin with a general component description if needed.

[Read the matching WEKO Surface Finishing page](#)

[Request a quotation: wekooem.com/contact](https://wekooem.com/contact)

Email: infous@wekosupply.com

REFERENCE AND DOCUMENT SCOPE

Prepared from the approved WEKO service/material scope at wekooem.com/capabilities/surface-finishing. This checklist is not a material certificate, test report, engineering approval, legal NDA or performance guarantee. Your released specification and agreed quotation control the order.